## RCRA PRELIMINARY ASSESSMENT SUPPLARY

Region VI. Technical Compliance Section

| FACILITY'S NAME(S): Sheppard Air Force Base                   |
|---|
| EPA ID NUMBER: TX3571524161                                   |
| ADDRESS: Hwy 240  |
| LOCATION: Vichita Falls, Texas                                |
| PREPARED BY: Charles Mark (TWC) DATE PREPARED: 6/3/86         |
| REVIEWED BY: Greg Detrecht (EPA) DATE REVIEWED: 6/13/86       |
| ANTICIPATED DRAFT PERMIT DATE: 7/86                           |
| ANY ON-GOING STATE/FED 264, 265, or 270 CORRECTIVE ACTION:    |
| DOES FACILITY HAVE A CERCLA FILL? YES X NO                    |
| CERCLIS HAZSIT NUMBER: TX11908                                |
| TYPE OF DRINKING WATER SUPPLY WITHIN A 3-MILE RADIUS: Unknown |
| TARGET POPULATION WITHIN A 3-MILE HADIUS:                     |
| Unknown   |
| RECOMMENDATIONS: S.I. X R.I. I.M. 3004(u) 3004(v)             |
| 3007  |
| Possible Enforcement Actions: 3008(e) 3008(h)                 |

Form: 4/10/86

9337838

- I. Preliminary Assessment of Prior or Continuing Releases of Solid Waste Hanagement Units (SWHUS)
  - A. Evaluation of Information
    - 1. The main purpose is to determine whether there has been or may have been a release(s) of hazardous waste or hazardous constituents from any Skills which will require corrective action measures under Section 3004(u) of the RCRA Hazardous and Solid Waste Amendments (HSWA) of 1984. The SMHUS units of concern are:
      - a) SMMUs not regulated under RCRA; and
      - b) SMMs regulated under RCRA regardless of whether they are subject to ground water menitoring requirements.
    - 2. The purpose of this review is to:
      - a) Identify all SWMUs;
      - b) Identify if there has been prior or continuing releases of hazardous wastes or hazardous constituents from such units to any media (air, surface water, ground water, soil & subsurface gas);
      - c) Identify if such releases caused environmental contemination that would require corrective action; and
      - d) Determine what additional information or investigation is needed to clarify whether there has been a release or if a potential for a release exists.

## B. NUMBER OF SOLID WASTE HANAGEMENT UNITS (SWMU): 69

| LIST OF SHAU                      | REGULATED BY RCRA* | STATUS** | SUBJECT TO<br>GWM SUBPART F |
|-----------------------------------|--------------------|----------|-----------------------------|
| (1) Container Storage Area        | Y                  | Proposed | 12                          |
| (2) Container Storage Area        | Ý                  | A        | H                           |
| (3-6) Four (4) Accumulation Areas | s Ý                | Ā        |                             |
| (7) Underground Tank              | ?                  | ?        |                             |
| (8-9) Two (2) Fire Protection     |                    | ·        |                             |
| Training Areas                    | H                  | I        | ĸ                           |
| (10) One (1) Fire Protection      |                    | •        |                             |
| Training Areas                    | H                  | A        |                             |
| (11-14) Four (4) Landfill Units   | i.<br>Hi           | 1/A      | 7                           |
| (15-17) Three (3) Solvent Pits    | N                  | 1        | 7                           |
|                                   |                    |          |                             |

| LIST    | OF SWAU                       | REGULATED<br>BY RCRA*                    | STATUS | SUBJECT TO<br>GWM SUBPART F |
|---------|-------------------------------|--|--------|-----------------------------|
| (18)    | Industrial Pit                | N  | A      | <u>\$</u> !                 |
| (19-20) | Two (2) Surface Impoundments  | a la | I      | it                          |
|         | Two (2) Low Level Radiosctive | ?  |        |                             |
|         | Wasta Cisposal Areas          | y  | Ī      | Ħ                           |
| (23)    | Sanatary Wastewater           |  |        |                             |
|         | Treatment System              | Ħ  | A      | N                           |
| (24)    | Gravel Lot (dump?)            | R  | A      | ¥                           |
| (25-28) | Four (4) Tanks                | H  | ?      | k .                         |
| (29-35) | Seven (7) 011-Water Seperator | rs li                                    | A      | tá                          |
|         | Thirty-Four (34) Grease Traps |  |        |                             |
|         | and Dump Tanks                | 8  | A      | 놝                           |

## C. NUMBER OF SHAU AT WHICH RELEASES HAVE BEEN IDENTIFIED: 3

(If any releases have been identified, an RI for the entire facility should be conducted, SI will not be necessary.)

| LIST OF SHAU               | RELEASE TO | NOTED DOCUMENTATION OF RELEASE         |
|----------------------------|------------|--|
| (1-3) Unlined Solvent Pits | Plum Creek | May 15, 1982, Waste<br>Nanagement Plan |

# D. NUMBER OF SWAU AT WHICH A RELEASE IS HIGHLY POSSIBLE: 4

(SIs should be conducted for each SWHU in this category unless an RI under C. has been indicated which will include this SWHUs).

LIST OF SWAU

REASONS (1.e., Weste characteristics, depth of GW, soil permeability, etc.)

(1-4) 4 Landfill Units On going RI to Characterize Units

# E. HUMBER OF SHILL WHERE A DETERMINATION OF RELEASE CAN NOT BE MADE DUE TO LACK OF INFORMATION: 57\*

(51s should be conducted for each SWAU in this category unless on RI under C. has been indicated which will include this SWAUs).

#### LIST OF SMMU

- (1) Industrial Oil Pit
- (2-3) 2 Surface Impoundments
- (4-5) 2-Low Level Redicactive Disposal Units
  - (6) Underground Tank
- (7-10) 4-Accumulation Areas-Container Storage
  - (11) Sanitary Wastewater Systems
  - (12) Gravel Lot-(Dumpl)
- (13-16) 4 Above Ground Tanks
- (17-23) 7 Gil-Water Separators
- (24-57) 34 Grease Trap and Dump Tanks
- F. HUMBER OF SWAU WITH MO INDICATED RELEASES: 2
  [Documentation is necessary for a SWAU to be included in this category).

### list of show

- (1) Proposed Container Storage Area (RCRA)
- (2) Container Storage Area (RCKA)

## 11. RECOMMENDATIONS: (EPA. STATE and/or CONTRACTOR)

Three (3) Fire Protection Training Areas (TWC did not address these units in the PA.)

### RECOMMENDATION MADE BY EPA AND THE

| SWAU   | OM<br>KOLTJA | SITE<br>INVESTIGATION | HEMEDIAL<br>INVESTIGATION (REASONING)         |
|--|--------------|-----------------------|---|
| Proposed Container<br>Storage Area           | EPA, TWC     |                       |   |
| Container Storage<br>Area                    | EPA, THC     |                       |   |
| Underground Tank 4 Accusulation              |              | EPA, TWC              |   |
| Areas  |              | EPA, THE              |   |
| 4 Landfill Units                             |              | HO. 1 and Ho. 2       | EPA & THC-On going study                      |
| 3 Unlined Splyent<br>Pits                    |              |                       | EPA 1 TVC-Release to Plum creek -On going fil |
| Industrial Oil Pit                           |              | EPA, TWC              |   |
| 2 Surface<br>Impoundments                    |              | epa, Twc              |   |
| Z Low Level<br>Radioactive Disposal<br>Units |              | EPA, THC              | 1   |
| Sanitary Waste-<br>Water Treatment<br>System |              | EPA, TNC              |   |
| Gravel Lot-(Dump?)                           |              | EPA, TWC              |   |
| 4 Above Ground Tanks                         |              | EPA, THC              |   |
| 7-011 Water Separator                        |              | EPA, THC              |   |
| 34 Grease Traps<br>and Dump Tanks            |              | EPA, TWC              |   |

CONCUR! Lydin M. Goals Clife

DATE: 6/13/86